

Safety Patrol & Defect Log

Date	Start time	End Time	Inspectors Name	Road Conditions				Weather Conditions				Route
				Dry	Wet	Snow	Ice	Fine	Rain	Snow	Fog	
11-01-2021	08:50am	14:50pm										<p>A470 C.B. Gwynedd/Mallwyd to Llanurig R/A – No Defect</p> <p>A44 – Llangurig R/A to C.B. Ceredigion (Eisteddfa Gerrig) – No Defect</p> <p>A489 – A470 Caersws junction to A483 Dolfor R/A/bypass. – No Defect</p> <p>A489 – Cemmaes Road R/A to A487 Machynlleth Clock – No Defect</p> <p>A487 – C.B.Ceredigion to C.B.Gwynedd (Dyfi Bridge) – No Defect</p> <p>Route driven in both directions.</p>

Defect Details

