

## Safety Patrol & Defect Log

Date	Start time	End Time	Inspectors Name	Road Conditions				Weather Conditions				Route
				Dry	Wet	Snow	Ice	Fine	Rain	Snow	Fog	
1-3-2021	09:30am	15:30pm	[REDACTED]									<p><b>A470 C.B. Gwynedd/Mallwyd to Llanurig R/A – No Defect</b></p> <p><b>A44 – Llanurig R/A to C.B. Ceredigion (Eisteddfa Gerrig) – See below</b></p> <p><b>A489 – A470 Caersws junction to A483 Dolfor R/A/bypass. – No Defect</b></p> <p><b>A489 – Cemmaes Road R/A to A487 Machynlleth Clock – No Defect</b></p> <p><b>A487 – C.B.Ceredigion to C.B.Gwynedd (Dyfi Bridge) – No Defect</b></p> <p><b>Route driven in both directions.</b></p>

Defect Details

Time	Road No/ Route	Defect Description	General location/ Link and Section/ GPS Co-Ordinates	Called through to Bronze/ARM ( Yes/No)	Called through to P/A (Yes/No)	Defect recorded on WFE (Yes/No)
14:00pm	A44	Pothole ORD-NM2048721	A44 opposite Sweet Lamb junction	No	Yes	No
14:00pm	A44	Loose rocking gully ORD-NM2048722	A44 Plas y bwlch and Rhoscastell.	No	Yes	No