

## Safety Patrol & Defect Log

Date	Start time	End Time	Inspectors Name	Road Conditions				Weather Conditions				Route
				Dry	Wet	Snow	Ice	Fine	Rain	Snow	Fog	
08-3-2021	09:30am	15:30pm	[REDACTED]									<p><b>A470 C.B. Gwynedd/Mallwyd to Llanurig R/A – See below</b></p> <p><b>A44 – Llangurig R/A to C.B .Ceredigion (Eisteddfa Gerrig) – See below</b></p> <p><b>A489 – A470 Caersws junction to A483 Dolfor R/A/bypass. – No Defect</b></p> <p><b>A489 – Cemmaes Road R/A to A487 Machynlleth Clock – No Defect</b></p> <p><b>A487 – C.B.Ceredigion to C .B.Gwynedd (Dyfi Bridge) – No Defect</b></p>

