## **Safety Patrol & Defect Log**

Salety Fation & Defect Log																		
Date	Start time	End Time	Inspectors Name			Road Conditions				Weather Conditions					Route			
18/02/202 1	08.25	13.05			Dry	Wet	Snow	Snow Ice Fine		Ra	ain	Snow Fo		=		4489M, <i>l</i> A470M	489M,A487M, A470M	
	<u>Defect Details</u>																	
Time	Road No/ Route	XSP	-			General location/ Link and Section/ GPS Co-Ordinates					Called through to Bronze/ARM ( Yes/No)						recorded E (Yes/No)	
10.18	A470	Left Carriageway	Pothole		250	250m past sarn railway bridge, carno.					emailed			Yes		Yes		