

Safety Patrol & Defect Log

Date	Start time	End Time	Inspectors Name	Road Conditions				Weather Conditions				Route
				Dry	Wet	Snow	Ice	Fine	Rain	Snow	Fog	
22-2-2020	09:30am	15:30pm										<p>A470 C.B. Gwynedd/Mallwyd to Llanurig R/A – See below</p> <p>A44 – Llanurig R/A to C.B .Ceredigion (Eisteddfa Gerrig) – No Defect</p> <p>A489 – A470 Caersws junction to A483 Dolfor R/A/bypass. – No Defect</p> <p>A489 – Cemmaes Road R/A to A487 Machynlleth Clock – No Defect</p> <p>A487 – C.B.Ceredigion to C .B.Gwynedd (Dyfi Bridge) – No Defect</p> <p>Route driven in both directions.</p>

Defect Details

Time	Road No/ Route	Defect Description	General location/ Link and Section/ GPS Co-Ordinates	Called through to Bronze/ARM (Yes/No)	Called through to P/A (Yes/No)	Defect recorded on WFE (Yes/No)
15:00pm	A470	Pothole	A470 close to Pontdolgoch Bridge	No	Yes	No
15:10pm	A470	Potholes	A470 Caersws junction with A489	NO	Yes	No