Safety Patrol & Defect Log

Salety Fation & Defect Log															
Date	Start time	End Time	Inspectors Name	Road Conditions				Weather Conditions						Route	
14/01/202 1	08.15	13.15		Dry	Wet	Snow	Ice	Fine	Ra	ain Snow Fo		Fo	~ I		.489M,A487M, A470M
	Defect Details														
Time	Road No/ Route	XSP	Defect Description		General location/ Link and Section/ GPS Co-Ordinates						Called through to Bronze/ARM (to I			ed through /A (Yes/No)	Defect recorded on WFE (Yes/No)
11.35	A487	R/H carriageway	Blocked catchpit	400	400m before Derwyn Las						Y				Υ