

Safety Patrol & Defect Log

Date	Start time	End Time	Inspectors Name	Road Conditions				Weather Conditions				Route
				Dry	Wet	Snow	Ice	Fine	Rain	Snow	Fog	
18-1-2021	09:40am	14:50pm		Dry	Wet	Snow	Ice	Fine	Rain	Snow	Fog	<p>A470 C.B. Gwynedd/Mallwyd to Llanurig R/A – No Defect</p> <p>A44 – Llangurig R/A to C.B. Ceredigion (Eisteddfa Gerrig) – No Defect</p> <p>A489 – A470 Caersws junction to A483 Dolfor R/A/bypass. – No Defect</p> <p>A489 – Cemmaes Road R/A to A487 Machynlleth Clock – See Below</p> <p>A487 – C.B.Ceredigion to C.B.Gwynedd (Dyfi Bridge) – No Defect</p> <p>Route driven in both directions.</p>

--	--	--	--	--	--	--	--	--	--	--	--	--

Defect Details

Time	Road No/ Route	Defect Description	General location/ Link and Section/ GPS Co-Ordinates	Called through to Bronze/ARM (Yes/No)	Called through to P/A (Yes/No)	Defect recorded on WFE (Yes/No)
12:30pm	A489	Pothole close to gully ORD-NM2047306 ORD-NM2047307	Approx 200m Machynlleth side of Llwyn Penegoes. Opposite Brynffynon 276,837/300,976	No	Yes	No