

Safety Patrol & Defect Log

Date	Start time	End Time	Inspectors Name	Road Conditions				Weather Conditions				Route
				Dry	Wet	Snow	Ice	Fine	Rain	Snow	Fog	
25-01-2020	09:30am	14:50pm		Dry	Wet	Snow	Ice	Fine	Rain	Snow	Fog	<p>A458 Llanerfyl Village to C.B.Gwynedd – No Defect</p> <p>A470 C.B. Gwynedd/Mallwyd to Llanurig R/A – See below</p> <p>A44 – Llangurig R/A to C.B.Ceredigion (Eisteddfa Gerrig) – No Defect</p> <p>A489 – A470 Caersws junction to A483 Dolfor R/A/bypass. – No Defect</p> <p>A489 – Cemmaes Road R/A to A487 Machynlleth Clock – No Defect</p> <p>A487 – C.B.Ceredigion to C.B.Gwynedd (Dyfi Bridge) – No Defect</p> <p>Route driven in both directions.</p>

Defect Details

Time	Road No/ Route	Defect Description	General location/ Link and Section/ GPS Co-Ordinates	Called through to Bronze/ARM (Yes/No)	Called through to P/A (Yes/No)	Defect recorded on WFE (Yes/No)
12:30pm	A470	Pothole. ORD-NM2047598-24HR ORD-NM2047599 -28 DAY All grid refs/location on work orders.	Approx 600m after Caersws 40mph sign R/H lane	No	Yes	Yes
14:24pm	A470	Pothole. ORD-NM2047622 - 24HR All grid refs/location on work orders.	Approx. 500m after Cwmllinau 40mph	No	Yes	Yes