



IRIS CONTRACT HIGHWAY INSPECTIONS



INSPECTIONS BY ROUTE & DEFECTS LOGGED

BATCH NO **INSPECTION DESCRIPTION**

25503 **SWTRA Safety Inspection (28 Day) of A465_28 on 19 December 2017**

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:PR

Inspection Date: 19/12/2017 10:50:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 19/12/2017

25089 **SWTRA Safety Inspection (28 Day) of A465_28 on 21 November 2017**

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:JM1

Inspection Date: 21/11/2017 12:12:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 21/11/2017

24659 **SWTRA Safety Inspection (28 Day) of A465_28 on 24 October 2017**

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR:PR

Inspection Date: 24/10/2017 10:37:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 24/10/2017

24246 **SWTRA Safety Inspection (28 Day) of A465_28 on 26 September 2017**

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:KS

Inspection Date: 26/09/2017 11:37:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 26/09/2017

23850 **SWTRA Safety Inspection (28 Day) of A465_28 on 29 August 2017**

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:JM1

Inspection Date: 29/08/2017 13:05:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 29/08/2017

23603 **SDG : Detailed Inspections All Items of A465 East Detailed on 11 August 2017**



IRIS CONTRACT HIGHWAY INSPECTIONS

INSPECTIONS BY ROUTE & DEFECTS LOGGED

BATCH NO **INSPECTION DESCRIPTION**

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

Inspection Date: 07/09/2017 09:42:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:KS

SURVEY METHOD: WALKED

[SWT16-23603-79](#)

CATEGORY 2.2, CARRIAGEWAY, BLACKTOP : FRETTING - 100 SQ M

[SWT16-23603-69](#)

CATEGORY 2.2, CARRIAGEWAY, BLACKTOP : FRETTING - 6 M

[SWT16-23603-70](#)

CATEGORY 2.2, CARRIAGEWAY, BLACKTOP : FRETTING - 50 SQ M

[SWT16-23603-71](#)

CATEGORY 2.2, CARRIAGEWAY, SINGLE CRACK - 4 M transverse crack

[SWT16-23603-72](#)

CATEGORY 2.2, CARRIAGEWAY, BLACKTOP : FRETTING - 100 M

[SWT16-23603-73](#)

CATEGORY 2.2, FENCES_AND_BARRIERS, DAMAGED/DEFORMED - 30 M

[SWT16-23603-74](#)

CATEGORY 2.2, CARRIAGEWAY, BLACKTOP : FRETTING - 40 SQ M

[SWT16-23603-75](#)

CATEGORY 2.2, FENCES_AND_BARRIERS, DAMAGED/DEFORMED - 6 M

[SWT16-23603-76](#)

CATEGORY 2.2, CARRIAGEWAY, POTHOLE - small pothole

[SWT16-23603-77](#)

CATEGORY 2.2, CARRIAGEWAY, BLACKTOP : FRETTING - 20 SQ M

23452 SWTRA Safety Inspection (28 Day) of A465_28 on 01 August 2017

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

Inspection Date: 01/08/2017 12:25:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:JM1

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 01/08/2017

23059 SWTRA Safety Inspection (28 Day) of A465_28 on 04 July 2017

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

Inspection Date: 04/07/2017 10:15:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:JM1

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 04/07/2017

22641 SWTRA Safety Inspection (28 Day) of A465_28 on 06 June 2017



IRIS CONTRACT HIGHWAY INSPECTIONS

INSPECTIONS BY ROUTE & DEFECTS LOGGED

BATCH NO **INSPECTION DESCRIPTION**

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

Inspection Date: 06/06/2017 10:56:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:JM1

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 06/06/2017

22245 SWTRA Safety Inspection (28 Day) of A465_28 on 09 May 2017

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

Inspection Date: 09/05/2017 11:30:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:JM1

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 09/05/2017

21836 SWTRA Safety Inspection (28 Day) of A465_28 on 12 April 2017

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

Inspection Date: 12/04/2017 10:26:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:PR

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 12/04/2017

21411 SWTRA Safety Inspection (28 Day) of A465_28 on 14 March 2017

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

Inspection Date: 14/03/2017 10:22:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:KC

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 14/03/2017

21009 SWTRA Safety Inspection (28 Day) of A465_28 on 14 February 2017

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

Inspection Date: 14/02/2017 09:27:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:KS

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 14/02/2017

20596 SWTRA Safety Inspection (28 Day) of A465_28 on 16 January 2017

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

Inspection Date: 16/01/2017 09:40:00

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR:KC

SURVEY METHOD: DRIVEN



IRIS CONTRACT HIGHWAY INSPECTIONS

INSPECTIONS BY ROUTE & DEFECTS LOGGED

BATCH NO INSPECTION DESCRIPTION

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 16/01/2017

19680 **SSI : Detailed Inspection - Road Studs: Conspicuity of A465 East Detailed (16/Novem**

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

Inspection Date: 19/01/2017 20:32:00

WEATHER: Fine

SURFACE CONDITION: WET

INSPECTOR:KS

SURVEY METHOD: DRIVEN

[SWT19-19680-2](#)

CATEGORY 2.2, ROAD STUDS, CONSPIC.STUD TEST FAILURE - 13 WHITES FAILED RC TEST

[SWT19-19680-27](#)

CATEGORY 2.1, ROAD STUDS, CONSPIC.STUD TEST FAILURE - 12 WHITES FAILED CONSPICUITY ON DOUBLE WHITE LINES

[SWT19-19680-3](#)

CATEGORY 2.3, ROAD STUDS, CONSPIC.STUD TEST FAILURE - 8 WHITES FAILED RC TEST