



# IRIS CONTRACT HIGHWAY INSPECTIONS



## INSPECTIONS BY ROUTE & DEFECTS LOGGED

**BATCH NO**      **INSPECTION DESCRIPTION**

**36901**      **SWTRA Safety Inspection (28 Day) of A465\_28 on 19 December 2019**

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:KC

Inspection Date: 20/12/2019 13:35:00

SURVEY METHOD: DRIVEN

**NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 20/12/2019**

**36488**      **SWTRA Safety Inspection (28 Day) of A465\_28 on 21 November 2019**

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:JM1

Inspection Date: 21/11/2019 12:24:00

SURVEY METHOD: DRIVEN

**NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 21/11/2019**

**36070**      **SWTRA Safety Inspection (28 Day) of A465\_28 on 22 October 2019**

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:JM1

Inspection Date: 22/10/2019 13:48:00

SURVEY METHOD: DRIVEN

**NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 22/10/2019**

**35625**      **SWTRA Safety Inspection (28 Day) of A465\_28 on 24 September 2019**

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR:SD

Inspection Date: 24/09/2019 11:16:00

SURVEY METHOD: DRIVEN

**NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 24/09/2019**

**35031**      **SWTRA Safety Inspection (28 Day) of A465\_28 on 27 August 2019**

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:RP

Inspection Date: 27/08/2019 10:50:00

SURVEY METHOD: DRIVEN

**NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 27/08/2019**

**34639**      **SWTRA Safety Inspection (28 Day) of A465\_28 on 30 July 2019**



# IRIS CONTRACT HIGHWAY INSPECTIONS

## INSPECTIONS BY ROUTE & DEFECTS LOGGED

**BATCH NO**      **INSPECTION DESCRIPTION**

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

Inspection Date: 30/07/2019 13:16:00

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR:RP

SURVEY METHOD: DRIVEN

**NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 30/07/2019**

**34206      SWTRA Safety Inspection (28 Day) of A465\_28 on 02 July 2019**

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

Inspection Date: 02/07/2019 10:46:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:RP

SURVEY METHOD: DRIVEN

**NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 02/07/2019**

**34119      SDG : Detailed Inspections All Items of A465 East Detailed ( Awaiting Return )**

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

Inspection Date: 22/10/2019 10:04:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:KC

SURVEY METHOD: WALKED

[SWT16-34119-50](#)

CATEGORY 2.2, CARRIAGEWAY, POTHOLE - 2X NO P/HOLES

[SWT16-34119-51](#)

CATEGORY 2.2, FENCES\_AND\_BARRIERS, DAMAGED/DEFORMED - MISSING RAILS/DAMAGED

[SWT16-34119-45](#)

CATEGORY 2.2, CARRIAGEWAY, BLACKTOP : FRETTING - 80 SQ MTS

[SWT16-34119-46](#)

CATEGORY 2.2, CARRIAGEWAY, BLACKTOP : FRETTING - FRETTING TO CENTRE LINE 20 MTS

[SWT16-34119-47](#)

CATEGORY 2.2, CARRIAGEWAY, BLACKTOP : FRETTING - 3 SQ MTS

[SWT16-34119-48](#)

CATEGORY 2.2, CARRIAGEWAY, BLACKTOP : FRETTING - 15 SQ MTS

[SWT16-34119-49](#)

CATEGORY 2.2, CARRIAGEWAY, PATCH - LOSS OF MATERIAL - 1 SQ MTR ADJ CENTRE LINE

**33777      SWTRA Safety Inspection (28 Day) of A465\_28 on 03 June 2019**

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

Inspection Date: 03/06/2019 11:06:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:RP

SURVEY METHOD: DRIVEN

**NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 03/06/2019**

**33335      SWTRA Safety Inspection (28 Day) of A465\_28 on 07 May 2019**



# IRIS CONTRACT HIGHWAY INSPECTIONS

## INSPECTIONS BY ROUTE & DEFECTS LOGGED

**BATCH NO**      **INSPECTION DESCRIPTION**

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

Inspection Date: 07/05/2019 15:06:24

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:RP

SURVEY METHOD: DRIVEN

**NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 07/05/2019**

**32921      SWTRA Safety Inspection (28 Day) of A465\_28 on 09 April 2019**

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

Inspection Date: 09/04/2019 10:49:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:SD

SURVEY METHOD: DRIVEN

[SWT13-32921-1](#)

CATEGORY 1, CARRIAGEWAY, POTHOLE - POTHOLE

[SWT13-32921-2](#)

CATEGORY 1, CARRIAGEWAY, POTHOLE - POTHOLE

**32488      SWTRA Safety Inspection (28 Day) of A465\_28 on 12 March 2019**

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

Inspection Date: 12/03/2019 11:04:00

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR:RP

SURVEY METHOD: DRIVEN

**NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 12/03/2019**

**32087      SWTRA Safety Inspection (28 Day) of A465\_28 on 12 February 2019**

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

Inspection Date: 12/02/2019 11:42:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:RP

SURVEY METHOD: DRIVEN

**NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 12/02/2019**

**31683      SWTRA Safety Inspection (28 Day) of A465\_28 on 15 January 2019**

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

Inspection Date: 15/01/2019 12:25:00

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR:PR

SURVEY METHOD: DRIVEN

**NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 15/01/2019**

**30985      SSI : Detailed Inspection - Road Studs: Conspicuity of A465 East Detailed on 03 Sept**



# IRIS CONTRACT HIGHWAY INSPECTIONS

## INSPECTIONS BY ROUTE & DEFECTS LOGGED

**BATCH NO**      **INSPECTION DESCRIPTION**

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

Inspection Date: 03/09/2019 14:32:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:SA

SURVEY METHOD: DRIVEN

[NPT42-30985-22](#)

CATEGORY 2.2, ROAD STUDS, CONSPIC.STUD TEST FAILURE - 25 WHITE NB

[NPT42-30985-20](#)

CATEGORY 2.2, ROAD STUDS, CONSPIC.STUD TEST FAILURE - 35 WHITE NB 24 WHITE SB