



IRIS CONTRACT

HIGHWAY INSPECTIONS



INSPECTIONS BY ROUTE & DEFECTS LOGGED

BATCH NO **INSPECTION DESCRIPTION**

48108 **SWTRA Safety Inspection (28 Day) of A465 East 28 on 24 May 2021**

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

Inspection Date: 24/05/2021 13:16:55

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR:PA

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 24/05/2021

47971 **SWTRA Safety Inspection (28 Day) of A465 East 28 on 18 May 2021**

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

Inspection Date: 18/05/2021 14:25:31

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:PR

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 18/05/2021

47814 **SWTRA Safety Inspection (28 Day) of A465 East 28 on 10 May 2021**

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

Inspection Date: 10/05/2021 11:33:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:PR

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 10/05/2021

47702 **SWTRA Safety Inspection (28 Day) of A465 East 28 on 04 May 2021**

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

Inspection Date: 04/05/2021 11:32:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:KC

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 04/05/2021

47536 **SWTRA Safety Inspection (28 Day) of A465 East 28 on 26 April 2021**

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

Inspection Date: 26/04/2021 13:31:39

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:PR

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 26/04/2021

47399 **SWTRA Safety Inspection (28 Day) of A465 East 28 on 20 April 2021**



IRIS CONTRACT HIGHWAY INSPECTIONS

INSPECTIONS BY ROUTE & DEFECTS LOGGED

BATCH NO **INSPECTION DESCRIPTION**

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

Inspection Date: 20/04/2021 11:54:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:PR

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 20/04/2021

47243 SWTRA Safety Inspection (28 Day) of A465 East 28 on 12 April 2021

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

Inspection Date: 12/04/2021 11:06:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:KC

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 12/04/2021

47130 SWTRA Safety Inspection (28 Day) of A465 East 28 on 06 April 2021

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

Inspection Date: 06/04/2021 11:37:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:KC

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 06/04/2021

46974 SWTRA Safety Inspection (28 Day) of A465 East 28 on 29 March 2021

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

Inspection Date: 29/03/2021 11:40:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:PR

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 29/03/2021

46833 SWTRA Safety Inspection (28 Day) of A465 East 28 on 23 March 2021

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

Inspection Date: 23/03/2021 11:26:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:PR

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 23/03/2021

46667 SWTRA Safety Inspection (28 Day) of A465 East 28 on 15 March 2021

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

Inspection Date: 15/03/2021 11:11:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:PR

SURVEY METHOD: DRIVEN



IRIS CONTRACT HIGHWAY INSPECTIONS

INSPECTIONS BY ROUTE & DEFECTS LOGGED

BATCH NO **INSPECTION DESCRIPTION**

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 15/03/2021

46556 **SWTRA Safety Inspection (28 Day) of A465 East 28 on 10 March 2021**

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

Inspection Date: 10/03/2021 10:54:00

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR:KC

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 10/03/2021

46381 **SWTRA Safety Inspection (28 Day) of A465 East 28 on 01 March 2021**

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

Inspection Date: 01/03/2021 11:29:00

WEATHER: Fog

SURFACE CONDITION: DRY

INSPECTOR:PR

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 01/03/2021

46242 **SWTRA Safety Inspection (28 Day) of A465 East 28 on 23 February 2021**

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

Inspection Date: 23/02/2021 09:53:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:PR

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 23/02/2021

45979 **SWTRA Safety Inspection (28 Day) of A465 East 28 on 09 February 2021**

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

Inspection Date: 09/02/2021 10:32:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:KC

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 09/02/2021

45658 **SWTRA Safety Inspection (28 Day) of A465 East 28 on 26 January 2021**

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

Inspection Date: 26/01/2021 12:08:00

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR:JM1

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 26/01/2021

45503 **SWTRA Safety Inspection (28 Day) of A465 East 28 on 18 January 2021**



IRIS CONTRACT HIGHWAY INSPECTIONS

INSPECTIONS BY ROUTE & DEFECTS LOGGED

BATCH NO **INSPECTION DESCRIPTION**

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

Inspection Date: 18/01/2021 11:47:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:PR

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 18/01/2021

45395 *SWTRA Safety Inspection (28 Day) of A465 East 28 on 12 January 2021*

Link/Section: - A465, 1046502006 - LLANGUA JN - GREENFIELDS JN

Inspection Date: 12/01/2021 10:34:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:KC

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 12/01/2021