



Llywodraeth Cymru  
Welsh Government

## Feedback form to Police/Welsh Government: Fatal Traffic Collision

|  |  |                                  |
|--|--|----------------------------------|
| <b>Police Force:</b>   | Dyfed Powys  |                                  |
| <b>Distribution list:</b>  | <a href="mailto:fatalcollisionnotifications@wales.gsi.gov.uk">fatalcollisionnotifications@wales.gsi.gov.uk</a>   |                                  |
| <b>Date and time of incident:</b>  | 16/11/2019   | Time (24Hr) 2200                 |
| <b>Location</b>  | <b>Grid ref.</b>   | Northing: 282400 Easting: 261006 |
| <b>Description</b>   | A487 Waunfawr/Commins Coch, Ceredigion SY23 3BW<br>Grid Reference SN 61006 82400   |                                  |
| <b>Weather:</b>  | Damp, intermittent light rain.   |                                  |
| <b>Road Conditions:</b>  | Damp surface<br>Down hill, right hand bend.  |                                  |
| <b>Street Lighting:</b>  | None at scene  |                                  |
| <b>Casualties (including age):</b>   | No. of Casualties: V1, 4 (3 serious, 1 female fatality, died later in hospital)<br>List ages: Driver 18, passengers 18(fatality) , 19 and 20<br>Occupants of V2 and V3 uninjured.  |                                  |
| <b>Vehicle details:</b>  | V1,Vauxhall Astra Sri CDTi 5 door saloon<br>V2, Audi A6 SE Quattro TDi Estate<br>V3, Vauxhall Corsa 5 door   |                                  |
| <b>Damage to road furniture:</b>   | Damage to tree base at nearside of road.   |                                  |
| <b>Brief description of incident:</b>  | V1 and V3 travelling towards Bow Street with V2 travelling in opposite direction. V1 has come into contact with the nearside hedge following travelling around a right hand bend. Having mounted the hedge, V1 collided heavily with a mature tree, causing it to rotate anticlockwise and fall back on to the road surface, coming into contact with V2. V3 has passed through the scene and stopped, with V2 rolling backwards post collision and colliding with the rear of V3. |                                  |
| <b>Any Highway implications, including contributory factors(debris in carriageway/standing water etc):</b> | None known or alleged.<br><br>No skid testing done at the scene due to the surface being heavily contaminated with engine oil from the Vauxhall Astra  |                                  |
| <b>Date and time of report/officer completing:</b>   | 18/11/2019<br>Garry Rees PC 317<br>Dyfed Powys Police Forensic Collision Investigation Unit  | Time (24Hr)1055                  |

**PROTECT-STAFF**



**Please use this box to add any additional comments if required:**

STORM DP-20191116-353

No skid tests conducted – post collision oil contamination of surface  
Scene laser scanned and photographed